

OLT-68154

1 1 Aug.69 22 432

P 112224Z AUG 69 FM NPIC WASHDC TO RHCOAAA/SAC OFFUTT AFB OMAHA NEB RHCOAAA/544TH ARTW OFFUTT AFB OMAHA NEB RUCILBA/100TH SRW OL 19 MCCOY AFB FLA RUWMODA/109TH SRW DAVIS MONTHAN AFB ARIZ RUWMODA/12 SAD DAYIS MONTHAN AFB ARIZ RUEBURA/NAVRECONTECHSUPPCEN SUITLAND MD RUEATIA/CIA WASH DC RUCRJCS/DIA RUWBKNA/15TH AF MARCH AFB RIVERSIDE CALIF RUEFHQA/HQS USAF BÌ

BECRET CITE NPIC 6795. SAC OLD HEAD FOR DOSR, DM4C, DIR, DISD, DISR; 100 SRW FOR DO, DCOI, DCM, AEMS; 12 SAD FOR DM; DIA FOR DIAXX-2; HQ USAF FOR

SUBJECT: EVALUATION OF OLD HEAD MISSION G-094

1. IMAGE QUALITY: THE OVERALL QUALITY OF THIS MISSION IS. A SLIGHT IMPROVEMENT IN THE IMAGE QUALITY IS APPARENT

PAGE 2 RUEADJU 0023 S E C R E T FROM THE BEGINNING OF THE MISSION TO THE END. INTERPRETATION SUITABILITY IS FAIR; WEATHER IS THE MAJOR DEGRADING FACTOR. CLOUD COVER AND HAZE OBSCURE 25 PERCENT OF THE ENTIRE MISSION 2. MISSION DATA:

A. G-094

B. 9 AUGUST 1969

C. B/24/U2R

MODE 5

T/O 1055Z, C/ON 1307Z

3401

G. 1/400

H. F/11

MINUS BLUE (WRATTEN 12)

NAV RECON TECH SUPPCEN, MX578

LEFT SIDE: 2.14; RIGHT SIDE:

3. ORIGINAL NEGATIVE:

EXPOSURE: SLIGHTLY UNDEREXPOSED IN THE BEGINNING OF THE MISSION TO SLIGHTLY OVEREXPOSED AT THE END OF THE MISSION.

B. DENSITY AND CONTRAST: GENERALLY MEDIUM THROUGHOUT THE MISSION.

IMAGED DEGRADATIONS:

RIGHT SIDE: SEE (3) BOTH SIDES. **(1)**

CY	OFFICE	-25X	1
	FILE	T .	1
2	CABLE SEC.		1
	PP&B/RD		1
	SECUR.		1
3,4	TSSG /A MSO	L	1
7.7	77		İ
	PSG/OC		1
4.5	RRD		ŀ
	REPRO		l
	AID		ŀ
	IEG		l
	PROD		ŀ.
	SCIEN	2 113	
	WEST		
	EAST		
	M&S		
	PGM		
	IAS		
	DIA-XX4		
	SPAD		
	DIA-AP		
	25)	(1]	
]	CMX	1	
	The second secon		
	The second second	1	

DISTRIBUTION



W. L. L. Land



- (2) LEFT SIDE: SEE (3) BOTH SIDES.
 (3) BOTH SIDES: EDGE FOG IS PRESENT INTERMITTENTLY ALONG BOTH EDGES THROUGHOUT THE MISSION. MINOR ROLLER CHATTER IS PRESENT ALONG THE INBOARD EDGE.
 - D. PHYSICAL DEGRADATIONS:
- (1) RIGHT SIDE: FOUR HEAT SPLICES AND TWO MANUFACTURER'S SPLICES ARE PRESENT IN THE MISSION MATERIAL.
- (2) LEFT SIDE: ONE HEAT SPLICE AND ONE MANUFACTURER'S SPLICE ARE PRESENT IN THE MISSION MATERIAL.
- E. AUXILIARY DATA: THE VERTICAL INDICATOR LIGHT SOURCE IS ALMOST COMPLETELY OBSCURED ON THE LEFT SIDE AND PARTIALLY OBSCURED ON THE RIGHT SIDE. ALL OTHER DATA RECORDING EQUIPMENT FUNCTIONED PROPERLY.
 - F. THE LAST TITLED FRAME IS 1609 FOR EACH SIDE.
- POSITIVES: PRINTING AND PROCESSING ARE ADEQUATE FOR INTERPRETATION PURPOSES.
- 5. REMARKS: THE 9L SIDE VERTICAL INDICTOR LIGHT SOURCE HAS BEEN ALMOST COMPLETELY OBSCURED ON THE PAST SIX MISSIONS EMPLOYING THIS CAMERA. GP-1 6 B C R E T

-- END OF MESSAGE --